

DO NOT ISSUE ANY HOT WORK PERMITS UNTIL FURTHER NOTICE.

SOUTH PRODUCTION NOTES

June 29, 2014

Day Shift

BASF EMPLOYEES

57 Last Recordable

362 Last Lost Time

#1 MED / AI 5655:

Continue running.

Midnight shift:

Day shift:

Afternoon shift: Continue.

#1 RC / AI 5655:

HOLD.

Midnight shift: Early Saturday morning, calciner was shut down due to chain violently "jumping" on main wheel sprocket. This was reported to Leon Zavodnik. Maintenance lubricated chain with hopes that issue would be resolved, but chain was still jumping when calciner was up to temp. Inspection of wheel blocks indicated that two blocks were missing, and a third had welds breaking away. Leon notified again and calciner brought down. Hold until further notice (maintenance does have plan to work on blocks and possibly re-train calciner)

Day shift:

Afternoon Shift:

Exhaust to Trimer

#2 MED line/ Cu-0860:

Down until further notice-Monday morning meeting. L. Zavodnik-email(Cu 3818 lot 469 bags 12-17, lot 470 all bags good to go).

Midnight shift: Decision to stop made due to numerous bad calcined bags identified by lab. Hold until further notice.

Day Shift:

Afternoon Shift:

#2 RC/ Cu-0860:

Continue running.

Midnight Shift: Continue feeding. Please be sure to feed bags in batch order. A batch feeding log sheet was generated for this to determine if any bad batches can be identified after material is calcined.

Day shift:

Afternoon shift:

Exhaust to F1
TANK 7 / AMT for D-1799 NAQ:

Continue to monitor the tank.

Midnight shift: Continue to monitor

Day shift:

Afternoon Shift:

Old Pfaudler D-1799 NAQ:

Making batches. Ensure that the appropriate amount of time has passed before feeding the #3 dryer.

Midnight Shift: Continue

Day Shift:

Afternoon Shift:

#3 Dryer / D-1799 NAQ:

Continue

Midnight Shift: Continue feeding hoppers from east pfaudler

Day shift:

Afternoon Shift:

#3 RC / D-1799 NAQ:

Continue feeding.

Midnight shift: Continue

Day shift:

Afternoon Shift:

Exhaust to CTO

#4 RC / Cu-0226:

Continue running into drums.

Midnight Shift: Re-feeding drums 11-20 Lot 20- per B Grodecki. While in hopper, it was noticed that the 0226 was peppered with 5206 particles.

Grodecki was notified...these drums need to be set aside, will probably need to be picked.

Day shift:

Afternoon Shift:

Exhaust to Trimer

#5 RC / Cu-3818:

Having issues with roton blocking up and spillage from under-side of drums on feed end. Only use Phibrotech copper and will be discharged into a 120 bag.

Midnight Shift: Down...afternoon shift pulled roton lines apart and mess still needs to be cleaned up.

Day shift:

Afternoon shift:

Exhaust to 5A DC

#6 RC / Clean for Spheres:

Will need to put screener back together and get the line set up before starting.

When starting back up, do not use burner #9 per Elliott.

Midnight shift: No activity

Day Shift: No activity.

Afternoon shift: No activity.

Exhaust to Sly Scrubber

PK Blender / Hold for Pill Mix:

PK and building 9 cleaned. **HOLD**

Midnight Shift: No activity

Day shift:

Afternoon shift:

New Pfaudler / Clean for Cr-5655:

Prepare to repair Pfaudler/ vacuum lines were acid washed and rinsed.

During nozzle and screen change (completed), operator noticed corrosion falling out of pfaudler (came from around the vacuum arm flange). Liquid

weigh tank was also cleaned. **Maintenance called in contractor for inspection and repairs as needed. Actual date of repairs TBD.**

Midnight shift: No activity

Day shift: No activity but Work notification written to have contractor (Lucas) set up the blender for Chrome – 934248795.

Afternoon Shift:

Abbe Blender:

HOLD. Waiting on next run.

Midnight shift: Hold.

Day shift: HOLD

Afternoon Shift: Hold

National Dryer / Clean for 5655:

Schirmer finished bead blasting. Final operator cleaning and setup required.

Midnight Shift: No activity

Day shift: No activity.

Afternoon Shift: No activity.

Tower 3 / Cu-0860:

Loaded and running Cu-0860 Lot 152.

Midnight Shift: Running...T3 should come down Sunday night

Day shift:

Afternoon shift:

Tower 6 / Cu-0860:

Loaded and Running.

Midnight Shift: Running

Day shift:

Afternoon shift:

North Screener / Cu 0860:

We need to double band all of the socks to the bins BEFORE OPENING ANY BINS – use the newly acquired adjustable quick disconnect hose clamps. Make sure that we hit the MOD rate.

Midnight shift: Continue

Day shift:

Afternoon Shift:

South Screener / Cu-1230:

We need to double band all of the socks to the bins BEFORE OPENING ANY BINS – we have now in place the newly acquired adjustable quick disconnect hose clamps .

Midnight shift: Continue...work order written to have hoist chain put back into box by maintenance.

Day shift:

Afternoon Shift:

#2662 (east) Pill Machine / Zr-0403 1/8: Hold

DC back together, pill machine in place. East machine not started yet. Look at changing all DC and delivery hoses, as needed.

Midnight shift: No activity

Day Shift: No activity

Afternoon shift: No activity.

#2664 (west) Pill Machine / Zr-0403 1/8: Hold

DC back together, pill machine in place. West machine was tested and looked / sounded good. Look at changing all DC and delivery hoses, as needed.(6/17/14)

Midnight shift: No activity

Day Shift: No activity

Afternoon shift: No activity

TK #2 / V 2010:

Had issues loading saggars directly from bag, stopped loading due to incident on afternoon shift. Discussed with L. Zavodnik regarding unloading bag to cart and then filling saggars as has been done in past.

Midnight shift: After reviewing Ray Navarro's quick ppt and discussion with Leon Z, inspected the current set-up and instructed operators to use improved PPE (racal, papr). Bag was supported over cart frame, bag opened and material slowly entered cart with little/no dusting. Top saggars also not being loaded (keep in place, only empty). Advised Leon Z that no issues occurred, continued loading.

Day Shift:

Afternoon shift:

Miscellaneous:

Vertical dust collector – Ameriwaste will be taking down clean side duct work and cleaning top of dust collector and duct (Wednesday / Thursday).

Maintenance is still working on roto-lock. Once all is done – bags can be re-installed.

Work Orders:

***Work notification written to have contractor set up the New Pfaudler for the upcoming Chrome run.**

***Work notification written to have electrician look at #2664 Horne Machine – Table error.**